



## Quick Start for FSC - Step by step from graphical curve to table values




### Step 1

Scan or ScreenShot the current/time diagram representing the tripping characteristic and insert it into any kind of document (e.g. MS Word, Excel or PowerPoint)


## Quick Start for FSC - Step by step from graphical curve to table values




**Step 2**  
Insert the graphic file "logarithmic  
scale.gif" as well




## Quick Start for FSC - Step by step from graphical curve to table values




Quick Start for FSC - Step by step from graphical curve to table values




## Quick Start for FSC - Step by step from graphical curve to table values



## Quick Start for FSC - Step by step from graphical curve to table values




## Quick Start for FSC - Step by step from graphical curve to table values





## Quick Start for FSC - Step by step from graphical curve to table values





## Quick Start for FSC - Step by step from graphical curve to table values

